



FACILITY COMPLIANCE INSPECTION REPORT

Division of Waste Management Solid Waste Section

UNIT TYPE:												
Lined MSWLF		LCID		YW		Transfer		Compost		SLAS	X	COUNTY: Wilson PERMIT NO.: SLAS-98-11 FILE TYPE: COMPLIANCE
Closed MSWLF		HHW		White goods		Incineration		T&P		FIRM		
CDFL		Tire T&P / Collection		Tire Monofill		Industrial Landfill		DEMO		SDTF		

Date of Site Inspection: 5/2/2013 **Date of Last Inspection:** 12/7/2012

FACILITY NAME AND ADDRESS:

*Allen Roberson
Roberson Septic Service
6049 US 301 N.
Elm City, NC 27822*

GPS COORDINATES:

N: 35.69186

W: -77.79693

FACILITY CONTACT NAME AND PHONE NUMBER:

Name: *Allen Roberson*
Telephone: *252-236-5725*
Email address: *allen@robersonsepticsservice.com*
Fax: *252-236-3813*

FACILITY CONTACT ADDRESS:

Same as above

PARTICIPANTS: *Chester Cobb*

STATUS OF PERMIT: *Active*

EXPIRES: *6/25/2013*

PURPOSE OF SITE VISIT: *Routine*

STATUS OF PAST NOTED VIOLATIONS:

No violations noted on the inspection conducted on 12/7/12.

OBSERVED VIOLATIONS:

NONE

The item(s) listed above were observed by Section staff and require action on behalf of the facility in order to come into or maintain compliance with the Statutes, Rules, and/or other regulatory requirements applicable to this facility. Be advised that pursuant to N.C.G.S. 130A-22, an administrative penalty of up to \$15,000 per day may be assessed for each violation of the Solid Waste Laws, Regulations, Conditions of a Permit, or Order under Article 9 of Chapter 130A of the N.C. General Statutes. Further, the facility and/or all responsible parties may be subject to enforcement actions including penalties, injunction from operation of a solid waste management facility or a solid waste collection service and any such further relief as may be necessary to achieve compliance with the North Carolina Solid Waste Management Act and Rules.

FACILITY COMPLIANCE INSPECTION REPORT
Division of Waste Management
Solid Waste Section

Page 2 of 2

ADDITIONAL COMMENTS

1. The appropriate signage was up at the front entrance and at a side entrance from a house.
2. Access road was in good shape.
3. Markers up.
4. No septage discharges noticed outside of the permitted field boundaries.
5. No application issues noticed.
6. No crop had been planted on the fields yet.
7. pH not checked. No application at time of inspection.
8. No objectionable odors noticed today.
9. No issues noticed with any of the setbacks.
10. Records not checked.
11. No violations noticed today.

Please contact me if you have any questions or concerns regarding this inspection report.



Chester R. Cobb

Regional Representative

Phone: (919) 707-8283.

Sent on: 7/30/13		Email		Hand delivery	X	US Mail		Certified No. <u> </u>
------------------	--	-------	--	---------------	----------	---------	--	-------------------------